

Inspector: Ryan Sullivan Start Date: 10/01/2018

Inspection Information			
1. Date of Inspection		09/28/2018	
2. Inspectors Present		Ryan Sullivan	
3. Other Persons Attending Inspec	3. Other Persons Attending Inspection		
Name	Phone	Owner/Engineer/Other	
Mr. Kornegay		Owner	
PJ		Other	
4. Is this a follow-up inspection?		Yes V No NA	
Observation/Instrumentat			
1. Estimate the current level of th	e water in the reservoir:	Breached	
Dam breached during Hurricane	Florence and is holding little to no	water.	
2. Describe the current weather &	conditions:	Sunny	
3. Recent rainfall quantity:		2" or greater	
Hurricane Florence brought ~20"	Hurricane Florence brought ~20" of rain the week before.		
4a. Are Piezometers or Observation	Yes V No		
4b. (If Present:) Condition of Piez			
5a. Is a Staff Gauge or Recorder p	Yes V No		
5b. (If Present:) Condition of Stat	f Gauge or Recorder		
6a. Are Measurement Weirs Prese	nt?	Yes V No	
6b. (If Present:) Condition of Wei	rs:		
7a. Number of Spillways Present		0	
The owners did not believe there was a spillway, though they were somewhat unfamiliar with the dam. No spillway observed.			
7b. Type of Spillways Present			
8. Other:			
9. Additional Comments (Refer to	item number if applicable)		
Embankment: Crest			
Is this section applicable for this of	dam?	✓ Yes ☐ No	



Inspector: Ryan Sullivan

Embankment: Crest

1. Grass Cover Action Required

Little to no grass cover.



Photo Taken: 9/28/2018 1:53:18 PM

2. Deleterious Vegetation

Action Required

Brush and woody vegetation observed on crest. See above picture

3. Trees Action Required

Dam is covered in trees greater than 4" in diameter.



Photo Taken: 9/28/2018 1:53:18 PM

4. Animal Activity

Monitor

Could not inspect full dam due to breach.


5. Surface Cracking

Monitor

Could not inspect full dam due to breach.



Inspector: Ryan Sullivan





Inspector: Ryan Sullivan Start Date: 10/01/2018

Embankment: Crest			
11. Other:			
12. Embankment: Crest Condition	Needs Permitted Repair(s), Condition Prevented Full Inspection		
Violation Determined: 10/1/2018 DAMMAINTREP			
13. Additional Comments (Refer to item number if applicable)			
Concrete/Masonry Dams: Crest			
Is this section applicable for this dam?	Yes Vo		
1. Surface Conditions			
2. Horizontal Alignment			
3. Vertical Alignment			
4. Condition of Joints			
5. Unusual Movement			
6a. Are Alterations/Repairs Present?	Yes No		
6b. (If Present:) Alterations/Repairs Condition			
7. Other:			
8. Concrete/Masonry Dam Crest Condition			
9. Additional Comments (Refer to item number if applicable)			
Embankment: Upstream Slope			
Is this section applicable for this dam?	✓ Yes No		
1. Grass Cover	Action Required		
Little to no grass cover.			



Inspector: Ryan Sullivan

Embankment: Upstream Slope

2. Deleterious Vegetation

Action Required

Brush and woody vegetation observed on the upstream slope.



Photo Taken: 9/28/2018 1:53:14 PM

3. Trees Action Required

Several trees greater than 4" in diameter observed on upstream slope.



Photo Taken: 9/28/2018 1:52:35 PM

4. Animal Activity Monitor

Could not inspect the full dam due to breach.

5. Surface Cracking Monitor

Could not inspect full dam due to breach.

6. Subsidence, Sinkhole Monitor

Could not inspect full dam due to breach.



Inspector: Ryan Sullivan Start Date: 10/01/2018

mbankment: Upstream Slope	
7. Slide, Slough, Scarp	Monitor
Could not inspect full dam due to breach.	
8. Groins	Action Required
Could not inspect full dam due to breach. Left upstream groin h	nad large trees and vegetation.
9. Erosion	Action Required
Full breach through center of the dam.	
10a. Slope Protection/Armoring Present?	Yes V No
10b. (If Present:) Slope Protection/Armoring	
11a. Alterations/Repairs Present?	Yes V No
11b. (If Present:) Alterations/Repairs Condition	
12. Other:	
13. Embankment: Upstream Slope Condition	Needs Permitted Repair(s), Condition Prevented Full Inspection
Violation Determined: 10/1/2018 DAMMAINTREP	
14. Additional Comments (Refer to item number if applicable)	
oncrete/Masonry Dams: Upstream Face	
Is this section applicable for this dam?	Yes V No
1. Surface Conditions	
2. Condition of Joints	
3. Unusual Movement	
4. Abutments	
5a. Alterations/Repairs Present?	Yes No
5b. (If Present:) Alterations/Repairs Condition	
6. Other:	
7. Concrete/Masonry Dams: Upstream Face Condition	
8. Additional Comments (Refer to item number if applicable)	



Inspector: Ryan Sullivan

Embankment: Downstream Slope

Is this section applicable for this dam?



1. Grass Cover Action Required

Little to no grass cover on downstream slope.



Photo Taken: 9/28/2018 1:56:35 PM

2. Deleterious Vegetation

Action Required

Brush and woody vegetation observed on downstream slope.

3. Trees Action Required

Trees greater than 4" in diameter observed on downstream slope.



Photo Taken: 9/28/2018 1:53:18 PM

4. Animal Activity

Monitor

Could not inspect full dam due to breach.



Inspector: Ryan Sullivan Start Date: 10/01/2018 Completed Date: 10/01/2018

Embankment: Downstream Slope	
5. Surface Cracking	Monitor
Could not inspect full dam due to breach.	
6. Subsidence, Sinkhole	Monitor
Could not inspect full dam due to breach.	
7. Slide, Slough, Scarp	Monitor
Could not inspect full dam due to breach.	
8. Groins	Action Required
Could not inspect full dam due to breach. Left d vegetation.	ownstream groin had large trees and wood
9. Erosion	Action Required
Large breach through center of the dam.	
10a. Slope Protection/Armoring Present?	Yes V No
10b. (If Present:) Slope Protection Condition	
11. Wet Areas	Monitor
Could not inspect full dam due to breach. Water	er still pooled behind dam due to breach.
	Photo Taken: 9/28/2018 1:56:15 PM
12a. Seepage	Yes No
Could not inspect full dam due to breach.	
12b. (If Present): Seepage Flow	
13a. Drainage System Present?	Yes V No
13b. (If Present:) Drainage System Condition	



Inspector: Ryan Sullivan Start Date: 10/01/2018

Embankment: Downstream Slope			
14a. Alterations/Repairs Present?	Yes V No		
14b. (If Present:) Alterations/Repairs Condition			
15. Other:			
16. Embankment: Downstream Slope Condition	Needs Permitted Repair(s), Condition Prevented Full Inspection		
Violation Determined: 10/1/2018 DAMMAINTREP			
17. Additional Comments (Refer to item number it	applicable)		
Concrete/Masonry Dams: Downstream	Face		
Is this section applicable for this dam?	☐ Yes ✓ No		
1. Surface Conditions			
2. Condition of Joints			
3. Unusual Movement			
4. Drains			
5. Leakage			
6. Abutments			
7a. Alterations/Repairs Present?	Yes No		
7b. (If Present:) Alterations/Repairs Condition			
8. Other:			
9. Concrete/Masonry Dam: Downstream Face Con	dition		
10. Additional Comments (Refer to item number it	f applicable)		
Downstream Area			
Is this section applicable for this dam?	✓ Yes No		



Inspector: Ryan Sullivan Start Date: 10/01/2018 Completed Date: 10/01/2018

Downstream Area	
Is Downstream Area clear?	Yes V No
Water pooled behind the dam from the breach, as wel	l as sand deposits from the eroded area. Photo Taken: 9/28/2018 1:56:15 PM
1. Trees	Monitor
Could not inspect full dam due to breach.	
2. Deleterious Vegetation	Monitor
Could not inspect full dam due to breach.	
3. Wet Areas	Monitor
Could not inspect full dam due to breach.	
4a. Seepage	Yes No V NA
Dam is breached and holding very little water.	
4b. (If Present): Seepage Flow	
5a. Boils	Yes No NA
Dam is breached and holding very little water.	
5b. (If Present): Boil Flow	
6a. Alterations/Repairs Present	☐ Yes ☑ No ☐ NA
6b. (If Present:) Alterations/Repairs Condition	
7. Other:	



Inspector: Ryan Sullivan Start Date: 10/01/2018

D	ownstream Area		
	8. Downstream Area Condition	Needs Maintena Needs Permitted Repair(s), Condi Prevented Full Inspection	d
	Violation Determined: 10/1/2018 DAMMAINTREP		
	9. Additional Comments (Refer to item number if applicable)		
S	pillways: Erodible Channel		
	Is this section applicable for this dam?	Yes V No	
	Could not inspect full dam due to breach.		
	1. Location		
	2. Grass Cover		
	3. Deleterious Vegetation		
	4. Trees		
	5. Animal Activity		
	6. Subsidence, Sinkhole		
	7. Slide, Slough, Scarp		
	8. Erosion		
	9. Debris		
	10. Flowing?	Yes No	■ NA
	11a. Alterations/Repairs Present	Yes No	■ NA
	11b. (If Present:) Alterations/Repairs Condition		
	12. Other:		
	13. Spillway: Erodible Channel Condition		
	14. Additional Comments (Refer to item number if applicable)		
S	pillways: Non-Erodible Channel		
	Is this section applicable for this dam?	Yes V No	
	Could not inspect full dam due to breach. Owner did not believe there was a	spillway.	
	1. Location		



Inspector: Ryan Sullivan Start Date: 10/01/2018

Spillways: Non-Erodible Channel	
2. Approach Area	
3. Weir/Control	
4. Sidewalls	
5. Channel Floor	
6. Condition of Joints	
7. Surface Condition	
8. Unusual Movement	
9. Discharge Channel	
10. Debris	
11. Flowing?	Yes No NA
12a. Boils	Yes No NA
12b. (If Present): Boils	
13a. Alterations/Repairs Present	Yes No NA
13b. (If Present:) Alterations/Repairs Condition	
14. Other:	
15. Spillway: Non-Erodible Channel Condition	
16. Additional Comments (Refer to item number if applicable)	
Spillways: Inlet Structure	
Is this section applicable for this dam?	Yes Vo
Could not inspect full dam due to breach. Owner did not believe there was observed.	a spillway. None
1. Location	
2a. Intake Structure	
2b. Intake Structure Types	
3. Trashrack	
4a. Low-Level Valve Present?	Yes No NA
4b. (If Present:) Low-Level Valve Condition	
5. Debris	



Inspector: Ryan Sullivan Start Date: 10/01/2018

Spillways: Inlet Structure		
6a. Repairs/Alterations Present	Yes No	■ NA
6b. (If Present:) Alterations/Repairs Condition		
7. Other:		
8. Spillway: Inlet Structure Condition		
9. Additional Comments (Refer to item number if applicable)		
Spillways: Outlet Works		
Is this section applicable for this dam?	Yes V No	
Could not inspect full dam due to breach. Owner did not believe there was a observed.	spillway. None	
1. Location		
2a. Outlet Structure		
2b. Outlet Structure Type		
3. Outlet Pipe		
4. Primary Closure/Control		
5. Secondary Closure/Control (If Applicable)		
6. Unusual Movement		
7a. Seepage	Yes No	■ NA
7b. (If Present): Seepage		
8. Stilling Basin		
9. Normal Flow Quantity		
10. Low-Level Flow Quantity		
11a. Alterations/Repairs Present	Yes No	■ NA
11b. (If Present:) Alterations/Repairs		
12. Other:		
13. Outlet Works Condition		
14. Additional Comments (Refer to item number if applicable)		
Emergency Action Plan		
Is this section applicable for this dam?	Yes Vo	



Inspector: Ryan Sullivan Start Date: 10/01/2018

Emergency Action Plan				
1. Date of last update of emergency plan:				
2a. EAP provided by owner?	Yes No	■ NA		
2b. (If EAP was not provided, was a copy of the EAP form left with the owner?)	Yes No	■ NA		
3. Does EAP contain emergency alert plan?	Yes No	■ NA		
4. Does EAP contain specific actions to take if the dam has failed or is failing?	Yes No	■ NA		
5. Additional Comments (Refer to item number if applicable)				
Downstream Hazard Check				
1. Satellite Imagery	Yes No	■ NA		
Photo Taken:	10/1/2018 2:43:12 PM			
2. Inundation Map	Yes V No	■ NA		
3. Structures/Developments	Yes Vo	■ NA		
4. Roads/Railways	Yes No	■ NA		
Judson Road is ~1200ft downstream.				
5. Utilities	Yes 🗹 No	■ NA		
6. Consider For Reclass?	Yes No	■ NA		
Low traffic Judson Road fairly close downstream, appeared to have taker hurricane.	n damage during the	;		
7. Additional Comments (Refer to item number if applicable)				

MCCOLL POND DAM: D0848

Dams Preliminary Inspection Form

Inspector: Ryan Sullivan



Inspection Summary

1. Overall Condition (*Per National Inventory of Dams Definition)

Not Rated

-----NID Definitions-----

(SATISFACTORY) No existing or potential dam safety deficiencies are recognized.

Acceptable performance is expected under all loading conditions in accordance with

state engineer's rules and regulations for dams or tolerable risk guidelines.

(FAIR) No existing dam safety deficiencies are recognized for normal loading

conditions. Rare or extreme hydrologic and/or seismic events may result in a dam

safety deficiency. Risk may be in the range to take further action.

(POOR) A dam safety deficiency is recognized for loading conditions, which may

realistically occur. Remedial action is necessary. A POOR condition is used when

uncertainties exist as to critical analysis parameters, which identify a potential dam

safety deficiency. Further investigations and studies are necessary.

(UNSATISFACTORY) A dam safety deficiency is recognized that requires immediate

or emergency remedial action for problem resolution.

(NOT RATED) This should only be used if it is not possible to assess to dam's

condition due to site constraints on visibility on the day of inspection. If vegetation is a

problem the owner should be ordered perform maintenance to remove it before the

next visit.

3. Final Comments

Very large, full breach in the center of the dam. Looked to be at least ten feet wide.

Inspector: Ryan Sullivan

Start Date: 10/01/2018 Completed Date: 10/01/2018



Inspection Summary

Preliminary Dam Inspection Disclaimer:

The information contained in the preliminary inspection report is intended as an aid to identify those dams that require maintenance and/or repair actions to reduce their danger to human life or property only. It is not intended as professional engineering or consulting advice for conditions or situations present at individual dams. It is not a substitute for a detailed inspection, nor does it replace the need for services provided by registered professional engineers. If your dam is experiencing an unusual situation consult with engineering professionals to find an appropriate remedy. Preliminary inspections conducted by South Carolina Department of Health and Environmental Control (the Department) are provided "AS IS" and "as available", without warranties of any kind, either express or implied. Preliminary inspections consist only of a visual but technical examination of the dam and its appurtenant works. All findings are based solely on visual observations of the inspector at the time of the inspection. Common law holds that the storage of water is a hazardous activity and the Department does not assume any responsibility or risk for your actions or inactions. Dam owners are responsible for the safe operations and maintenance of their impoundment structures.

MCCOLL POND DAM (D0848) Violation List



Form	Determined	Description	Sec. #
Dams Preliminary Inspection Form	10/1/2018	Reference: DAMMAINTREP	
Dams Preliminary Inspection Form	10/1/2018	Reference: DAMMAINTREP	
Dams Preliminary Inspection Form	10/1/2018	Reference: DAMMAINTREP	
Dams Preliminary Inspection Form	10/1/2018	Reference: DAMMAINTREP	

10/01/2018 12:42 PM 17