DAM NUMBER	DAM NAME	Hazard	COUNTY	ASSESSMENT DATE	CONDITION	CREST	PRIMARY SPILLWAY	TREE DAMAGE	BREACH STATUS	EMERGENCY REPAIRS	RAINFALL	PIPING BOILS	EROSION	FULL INSPECTION REQUIRED	AUX SPILLWAY CONDITION	EROSION DESCRIPTION	COMMENTS	OWNER PRESENT
D0513	BAXLEY 501 POND DAM	Class 2 - Significant	Marion	9/9/2018	Damage - Not Severe	Freeboard > 1 ft.	Partial Flow	No Tree Damage	Not Breached	No	None	None	< 12"" Deep	***	No Flow	Previously recorded damage. Erosion near primary spillway and outlet	Water level much lower than usual.	
D0848	MCCOLL POND DAM	Class 3 - Low	Dillon	No Pre-Storm Assessment														
D1824	CRAWFORD POND DAM	Class 3 - Low	Chesterfield	No Pre-Storm Assessment														
D3188	LAKEWIND DAM	Class 2 - Significant	Chesterfield	9/10/2018	***												Primary riser failed in 2015. Pond has not been repaired and is drained. No flow observed through the damaged riser.	
D3430	McMEEKIN POND DAM	Class 3 - Low	Marlboro	No Pre-Storm Assessment														
D3441	MCLAURINS MILLPOND DAM	Class 2 - Significant	Marlboro	9/10/2018	Damage - Not Severe	Freeboard > 1 ft.	Partial Flow		Not Breached	No	None				No Flow		One 12" flash board is removed and the WSE is going down.	No
D3450	DAVIDS MILLPOND DAM	Class 2 - Significant	Marlboro	9/10/2018	***	***	No Flow	***	Not Breached	***	< 2""			***	No Flow	***	three flash boards are removed but at this time no flow is observed.	No
D3453	COVINGTON MILLPOND DAM	Class 3 - Low	Marlboro	No Pre-Storm Assessment														
D3530	LAKE DARPO DAM	Class 3 - Low	Darlington	No Pre-Storm Assessment														
D3532	JORDAN POND DAM	Class 2 - Significant	Darlington	9/10/2018	No Damage	Freeboard > 1 ft.	Partial Flow	No Tree Damage	Not Breached	No	< 2""	None	< 12"" Deep	***	No Flow	Very minor on upstream slope recently repaired.	Brush needs trimming but no apparent issues. Recommended clearing auxiliary spillway. And minor debris/weeds on spillway.	Yes
D3539	SPRING LAKE DAM	Class 3 - Low	Darlington	No Pre-Storm Assessment													·	