

Catherine E. Heigel, Director Promoting and protecting the health of the public and the environment

Certified Mail

November 2, 2015

JACOB SMITH, SOUTHERN PINE RANCH LLC 4774 REDBUD CT DECATUR, IL 62526

Re: SATCHER-SMITH POND DAM - D 4057

Edgefield County

To Whom It May Concern:

According to our records, you are listed as the Owner(s) of SATCHER-SMITH POND DAM. Based on a visual assessment of your dam following the recent flooding, it was noted that your dam is damaged and repairs and/or maintenance are needed to ensure your dam is in compliance with the South Carolina Dams and Reservoirs Act, S.C. Code Ann. 49-11-110, et seq., and Regulation 72-1, et seq.

Your dam, including spillways and all appurtenances, must be inspected by a South Carolina licensed professional engineer to assess the dam and identify any necessary repairs and/or maintenance. A detailed report of the engineer's assessment, including findings and recommendations, must be submitted by the engineer to the Department by February 2, 2016. This report must include a statement by the engineer that all maintenance actions needed have been completed. An application for a permit to make any necessary repairs must also accompany the detailed report submitted by your engineer. The application and other relevant information can be found on our website at http://www.scdhec.gov/environment/WaterQuality/DamsReservoirs/DamsPermitting.

All correspondence should be directed to:

Surface Water Monitoring and Dam Safety Section Bureau of Water, SCDHEC 2600 Bull Street Columbia, SC 29201 Email: response@dhec.sc.gov

Should you have any questions regarding the requirements of this letter, please call 803-898-1539.

Sincerely,

Charles M. Gorman, PG, Director

Division of Water Monitoring, Assessment & Protection

Bureau of Water

ENC: List of Engineers