Adrian Sand/Clay Pit : NXDW-HN3R-QFP

Mines - General Mine Operating Permit Inspection




Inspector: Caylie McCarthy Start Date: 12/20/2023 Completed Date: 12/20/2023

General Information	
1. Permit No.	GP1-002406
2. Inspection Date	12/20/2023
3. Company	Adrian Sand, LLC
4. Mine	Adrian Sand/Clay Pit
5. County	Horry
6. Inspection Type	Routine

7. General Observations

No active mining taking place. Stockpiling dirt only. Working on the right side of the property. Existing pond on the left of the property.



Adrian Sand/Clay Pit : NXDW-HN3R-QFP Mines - General Mine Operating Permit Inspection



Inspector: Caylie McCarthy Start Date: 12/20/2023 Completed Date: 12/20/2023

eneral Informat	ion		
	Dec 20, 2023 at 10:15 44 AM Conway SC 29526 United States	Photo Uploaded: 12/20/2023	
	Dec 20, 2023 at 10:03:31 AM Conway SC 29526 United States	Photo Uploaded: 12/20/2023	
8. Inspection Participa	ants		
8. Inspection Participa Name Brandon Grover	ants Title Operator	Organization	
Name	Title	Organization	
Name Brandon Grover	Title	Organization	
Name Brandon Grover	Title Operator		
Name Brandon Grover Derations 1A. Active mining?	Title Operator No active mining.		
Name Brandon Grover Derations 1A. Active mining? Stockpiling dirt only.	Title Operator No active mining. ed at site.		
Name Brandon Grover Derations 1A. Active mining? Stockpiling dirt only. 1B. Date mining cease	Title Operator No active mining. ed at site. ac?	No	
Name Brandon Grover perations 1A. Active mining? Stockpiling dirt only. 1B. Date mining cease 2. Affected Area ≤ 5 a	Title Operator No active mining. ed at site. ac?	No Yes	

Adrian Sand/Clay Pit : NXDW-HN3R-QFP Mines - General Mine Operating Permit Inspection



Inspector: Caylie McCarthy Start Date: 12/20/2023 Completed Date: 12/20/2023

Public Safety	
5. Mine depth \leq 20 feet?	Yes
6. Is perimeter fence necessary?	No
7. Entrance w/mud mat in place/maintained?	Yes
8. Highwalls sloped 3:1 when site inactive?	NA - Not Applicable
9. Mining on 3:1 slope or highwalls< 10 feet?	NA - Not Applicable
10A. Mine> 1,000 ft. from school, playground, hospital?	Yes
11A. Mine > 500 ft from houses?	Yes
Reclamation Activities	
12. State Final Reclamation Land use	Lake/Pond
13. Reclamation proceeding where feasible?	NA - Not Applicable
15. Debris removal proceeding as feasible/necessary?	NA - Not Applicable
16. Seeding & fertilizing proceeding when appropriate?	NA - Not Applicable
17. Vegetation established for reclamation maintained?	NA - Not Applicable
Environmental Protection	
19. BMPs (silt fences, brush barriers etc.)?	NA - Not Applicable
20. Sediment basins functioning properly?	NA - Not Applicable
21. Temporary vegetation for erosion control?	NA - Not Applicable
22. Pump intake minimum 3 ft. from bottom of sump?	NA - Not Applicable
23. Cultural and Historic areas protected?	1 - Adequate (only minor and/or potentia problems exist)
24. Wetlands Protected & buffers maintained?	1 - Adequate (only minor and/or potentia problems exist)
25. Runoff/discharge controlled to prevent flooding?	NA - Not Applicable
26. Fugitive Dust Controlled?	1 - Adequate (only minor and/or potenti problems exist)

Adrian Sand/Clay Pit : NXDW-HN3R-QFP

Mines - General Mine Operating Permit Inspection



Inspector: Caylie McCarthy Start Date: 12/20/2023 Completed Date: 12/20/2023

Environmental Protection

27. Noise Controlled?

1 - Adequate (only minor and/or potential problems exist)

28. Equipment fueling area maintained

NA - Not Applicable

29. Other Comments Pertaining to this Section Mining has not started yet. Stockpiling dirt.

Adrian Sand/Clay Pit (NXDW-HN3R-QFP) Violation List

No Violations Found