

CDHEC UST Management

Public Record Posted Date: 10/19/2021

Public Record - Summary Information On Underground Storage Tanks (USTs) From 10/01/2020 To 09/30/2021

General Information

Total Number Of UST Facilities: 3,965
 Total Number Of USTs: 11,103

Summary Information For On-Site Inspections

Number Of UST Facilities Inspected: 3,241
 Inspection Period Dates: 10/01/2020 To: 09/30/2021
 Percent Compliance (Combined Measure): 45.29 %

Note: Tank, facility, and on-site inspection information is based on underground storage tanks regulated under Subtitle I that satisfy the definition of UST in 40 CFR 280.12, except for those tanks identified in 40 CFR 280.10(b) as excluded USTs and those deferred in 40 CFR 280.10(c). On-site inspections measure compliance with release detection and release prevention (technical compliance rate, state regulations, Subtitle I, etc.).

Summary Information For Releases:

Number Of Confirmed UST Releases: 213
 Release Reporting Period Dates: 10/01/2020 To: 09/30/2021

Summary Information For Release Sources And Causes:

Source/Location		Cause														
		Spill		Overfill		Phys/Mech Damage		Corrosion		Install Problem		Other		Unknown		
#	%	#	%	#	%	#	%	#	%	#	%	#	%	#	%	
TANK	55	25.94	0	0.00	0	0.00	4	7.27	0	0.00	0	0.00	51	92.73	0	0.00
PIPING	11	5.19	0	0.00	0	0.00	8	72.73	0	0.00	0	0.00	3	27.27	0	0.00
DISPENSER	13	6.13	0	0.00	0	0.00	13	100.00	0	0.00	0	0.00	0	0.00	0	0.00
STP	6	2.83	0	0.00	0	0.00	6	100.00	0	0.00	0	0.00	0	0.00	0	0.00
DELIVERY PROB	0	0.00	0	0.00	0	0.00	0	0.00	0	0.00	0	0.00	0	0.00	0	0.00
OVERFILL	5	2.36	0	0.00	5	100.00	0	0.00	0	0.00	0	0.00	0	0.00	0	0.00
OTHER	123	58.02	1	0.81	0	0.00	105	85.37	0	0.00	0	0.00	17	13.82	0	0.00
UNKNOWN	0	0.00	0	0.00	0	0.00	0	0.00	0	0.00	0	0.00	0	0.00	0	0.00
Totals	213		1	0.47	5	2.36	136	64.15	0	0.00	0	0.00	71	33.49	0	0.00

Note: Release, source and cause information is based on underground storage tanks regulated under Subtitle I that satisfy the definition of UST in 40 CFR 280.12. This report reflects data from releases reported to the Department during the time period of the report. Source and cause data were collected using on-site inspections and reports from facilities.

Note: "UNKNOWN" is based on releases discovered during tank removal operations or pre-buy assessments. The locations of these releases were not identifiable. "OTHER" is an identifiable source that does not fit specific locations identified in the chart.

Additional information on site-specific USTs such as compliance and releases may be obtained through contacting the Freedom of Information Office at 803-898-3880 or on-line at the UST Registry (WWW.SCDHEC.GOV).